

Save the Date! Thursday, March 15, 2018

EASA Root Cause Failure Analysis Class

@ Decatur Industrial Electric

Root Cause: Winding & Rotor Failures / Root Cause: Bearing & Shaft Failures

Cost: \$300 per person or \$275 per person if 2+ attendees from same company

Time: 8 AM to 5 PM CST (lunch will be provided)

Where: Decatur Industrial Electric / 1650 E. Garfield Ave. / Decatur, IL 62526

RSVP Options:

- Tell your D.I.E. Account Manager to "Sign me up!"
- Email Kelli at krunyon@decaturindustrial.com
- Call 217-428-6621 and ask for Kelli

One of the most important factors to consider when repairing motors is to understand why they failed. This seminar will focus on common as well as unusual types of failures broken down by components. This class is intended for anyone interested in understanding motor failures & addressing the root cause of failure rather than the symptom.

No PO needed until 2018!

Reservations cancelled after February 19, 2018 will not be issued a refund.



Jim Bryan, EASA Instructor

Jim Bryan is a technical support specialist with the Electrical Apparatus Service Association (EASA). Before joining EASA, Bryan worked for more than 20 years at Emerson Motor Company (Nidec Corporation) in St. Louis

Presented by:



**DECATUR
INDUSTRIAL
ELECTRIC**