Save the Date! Wednesday, March 22, 2023 EASA Root Cause Failure Analysis Class @ Decatur Industrial Electric

Root Cause: Winding & Rotor Failures / Bearing & Shaft Failures

Cost: \$300 per person or \$275 per person if 2+ attendees from same company.

Half off the true cost of class from EASA

Time: 8 AM to 5 PM CST (lunch will be provided)

Where: Decatur Industrial Electric / 1650 E. Garfield Ave. / Decatur, IL 62526

RSVP Options:

- Tell your D.I.E. Account Manager to "Sign me up!"
- Email rsvp@decaturindustrial.com

One of the most important factors to consider when repairing motors is to understand why they failed. This seminar will focus on common as well as unusual types of failures broken down by components. This class is intended for anyone interested in understanding motor failures & addressing the root cause of failure rather than the symptom.

Reservations cancelled after February 20, 2023 will not be issued a refund.



Tom Bishop, EASA Instructor, Senior Technical Support Specialist

Presented by:



